$\frac{1}{4}$ -14 x 0.88" HWH DP1 2 $\frac{1}{2}$" O/C

FILL VOIDS AT HIGH-RIB OVERLAP COMPLETELY WITH SEALANT (NOT BY IMP SUPPLIER)

NOTE: BUTYL SEALANT AND BUTYL TAPE TO RUN ACROSS FULL WIDTH OF PANELS; NOT SHOWN AT HIGH RIBS FOR CLARITY.

(1) ROW OF 1" x $\frac{3}{16}$" BUTYL TAPE SEALANT

FIELD-APPLIED $\frac{3}{8}$" BEAD OF NON-SKINNING BUTYL SEALANT

SUPPORT ANGLE AND FASTENERS BY OTHERS (NOT BY IMP SUPPLIER)

"SW-01" SADDLE WASHER W/ $\frac{1}{4}$ - 14 x _ HWH DP3 W/ WASHER SPACED __ O/C (PILOT HOLE RECOMMENDED)

CONTINUOUS $\frac{1}{2}$" Ø BEAD OF GUN-GRADE NON-SKINNING BUTYL SEALANT AT PANEL ENDLAP

CONTINUOUS $\frac{1}{2}$" Ø BEAD OF BUTYL SEALANT (CONNECT ENDS OF CAULK BEADS TO CLOSE AND BOX)

SECONDARY FRAMING (NOT BY IMP SUPPLIER)

NOTE: REFER TO SECTION 13.6 ON THE HR3 & HR5 INSULATED ROOF PANELS GENERAL INSTALLATION GUIDE FOR ADDITIONAL INFORMATION.

HR ROOF PANEL ENDLAP

(SECTION VIEW)

DETAIL: ENDLAP

APPLICATION:
HR ROOF, COMMERCIAL & INDUSTRIAL, COLD-STORAGE, COLD-CLIMATE

AWIP DETAIL NUMBER:
HRR-CICSCC-EL-001

SHEET: 1 OF 1

DATE: 11/02/23

DRAWN BY: MMF