



FIELD APPLIED  
BUTYL SEALANT  
WARM SIDE

NOTE: FILL EXTERIOR SIDE OF FEMALE JOINT  
CONTINUOUSLY APPROXIMATELY ONE HALF TO  
THREE QUATERS FULL. (DO NOT UNDERFILL)

## COOLER / FREEZER PANEL JOINT (TYPICAL)



929 ALDRIDGE ROAD, VACAVILLE, CA 95688  
PHONE: (707) 359-2280 FAX: (707) 359-2286

DETAIL:	COOLER / FREEZER PANEL JOINT	
APPLICATION:	COOLER / FREEZER STORAGE	
DATE: 03/14/07	JOB NO:	XXXXXXXXX
DRAWN: CLR	SHEET:	1 OF 1